

The Art of Industrial Intelligence

Release Notes

AVEVA Reports for Operations

Version 2023 R2

User Friendly Programming-Free™ Reporting for Automation

Contents

Release Notes	1
Summary of New Functionality and Enhancements for AVEVA Reports Release 2023 R2 (comparto to the original version 2023 Patch 2)	
Corrected Issues/SCRs (AVEVA Reports 2023 R2)	4
Summary of New Functionality and Enhancements for AVEVA Reports Release 2023 Patch 2 (compared to the original version 2023)	6
Corrected Issues/SCRs (AVEVA Reports 2023 Patch 2)	7
Summary of New Functionality and Enhancements for AVEVA Reports Release 2023 (compared the original version 2020 R2 SP1)	
Corrected Issues/SCRs (AVEVA Reports 2023)	11
Corrected Issues/SCRs (AVEVA Reports 2020 R2 SP1)	13
Summary of New Functionality and Enhancements for AVEVA Reports Release 2020 R2 (comparto the original version 5.0 R20-3)	
Corrected Issues/SCRs (AVEVA Reports Release 2020 R2)	16
Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R20-3 (compared to the original version 5.0 R20-2)	17
Corrected Issues/SCRs (Dream Report 5.0 R20-3)	18
Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R20-2 (compared to the original version 5.0 R20-1)	19
Corrected Issues/SCRs (Dream Report 5.0 R20-2)	21
Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R20-1 (compared to the original version 5.0 R19-3)	22
Corrected Issues/SCRs (Dream Report 5.0 R20-1)	24
Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R19-3 (compared to the original version 5.0 R2)	25
Corrected Issues/SCRs (Dream Report 5.0 R19-3)	27
Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R2 (compa	
Corrected Issues/SCRs (compared to the previous version 4.83)	32
System Requirements	35
To buy AVEVA Reports for Operations	36
Contact Technical Support	36

Summary of New Functionality and Enhancements for AVEVA Reports Release 2023 R2

(compared to the original version 2023 Patch 2)

	Module	Description
New Features		
	[Batch Manager]	External batches from event frame drivers Nested batches
	[Report Clusters]	Set of graphical objects organized as cluster(s) where clusters are used as part of the report batches representations.
	[Batch Object]	Cluster composition program for batch
	[CSV Alarms Importer]	CSV Alarms Importer provide possibility import Alarm and Audit logs from Siemens CSV files into MSSQL database
	[e-Signature]	e-Signature workflow allows to setup order for signees'.
Other Enhancements		
	[LUA]	New Lua function that can be called from Expression to log message into log file, the message is logged as Inform with Normal log level
	[Security Enhancements]	Product Cyber security Enhancement
Comm. Drivers updates		
	[IEC61850 RT Driver]	IEC 61850 real-time communication driver that enables users to connect with intelligent electronic devices (IED) at electrical substations
	[Alarm HDA Driver for PI AF Event Frames]	PI Historical Alarms driver that provides availability to report AF alarms
	[Event Frame Driver for PI AF Event Frames]	PI Event Frames driver allows user to retrieve Batches information from PI AF Event Frames.
	[Batches Management LUA based driver]	

Corrected Issues/SCRs (AVEVA Reports 2023 R2)

#SCRs	Module	Description
SD-3791	[Adv ODBC DRV]	Advanced ODBC driver script placing the WHERE close in a
		wrong order.
SD-3783	[AST Table]	Order of the tags in AST changed when one tag was removed from the list and another one was added.
SD-3782	[GENERATOR]	Possibility to set time for report generation - Event Time or Generation time as current time for delayed reports
SD-3776	[DESIGNER STUDIO]	Can't set drrepo project as startup project in Runtime Configuration
SD-3774	[Yokogawa Data Import Tool]	Fixed the issues with the table tChannel
SD-3773	[Yokogawa Data Import Tool]	Values with ID "52" and "53" for the column Execute are not logged in the table tOperateLogExecute.
SD-3772	[Yokogawa Data Import Tool]	Factor with ID "9" and Text "Web" is not logged in the table tOperateLogFactor.
SD-3770	[WEB API]	WebAPI issue when the URL for report has ipp's and report set to be refreshed the ipp's are not taken into consideration after refresh.
SD-3768	[WEB]	Add "Select All" button for Combo box
SD-3766	[WEB]	Combo Box value can`t be retrieved inside Pivot Group
SD-3765	[WEB]	Dynamic Tag Replacement is not applied to the objects in Pivot Group.
SD-3763	[WEB]	Web Portal must be opened on https protocol by default using a shortcut in RMC
SD-3762	[WEB]	Chart object with "Show prev. value if no data" disabled is not displaying data in the same way in PDF and in WEB.
SD-3759	[GENERAL]	SQL Table fails to get a result when SQL query name is passed from Combo Box
SD-3758	[WEB]	When using button submit second time, message displayed in English, although web portal configured in Russian and first message was displayed in Russian
SD-3756	[Citect RT Driver]	On adding tags with long names into item group from Citect studio crashes
SD-3753	[ODBC Driver]	ODBC driver fails to retrieve data from a table with the separate columns for date and time.
SD-3750	[Audit Trail]	No tags browse from AVEVA InSight Performance driver
SD-3749	[UM]	A possibility to add users' group which name contains spaces
SD-3747	[WEB]	DR Studio crashes upon attempt to add an item from Yokogawa driver when there are no Yokogawa files in the folder.
SD-3741	[GENERATOR]	Report Instance Information is not available in Pivot Group
SD-3740	[WEB]	Option for displaying big numbers (from project localization) doesn't applied for values of axis of web chart
SD-3738	[DRV ODBC HDA ITEM]	Table names appear in PDF report, although they shouldn't be displayed
SD-3737	[eSignature]	eSignature notification when non pdf report is generated
SD-3735	[STUDIO]	Carriage return symbol is added to a hyperlink in Web report

SD-3734	[DRV ROCKWELL	
	INFOPLATFORN HDA]	Logger crashes upon recording the analytical group
SD-3733	[CSV DRIVER]	CSV driver imports only a top row from the file where records
		are ordered by descending timestamps
SD-3732	[REMOTE DEV]	Memory leak in MTA calculation
SD-3731	[WEB]	Function current value from Kepware OPC DA Server brings N/A
SD-3730	[OPC UA DRIVER]	Cyrillic symbols are not displayed properly in browse of tags using OPC UA drivers
SD-3726	[DRV AVEVA ALMDB]	Operator name field for the Alarms Table is taken from the first event, which can be blank
SD-3725	[DRV OPC UA]	Norwegian symbols are garbled with OPC-UA driver
SD-3724	[DRV OPC UA HDA]	OPC UA Historical driver causes too many connections on the
		OPC UA Server side if tag addresses are not found on the
CD 2 T 22	SD CALAK	serve.
SD-3722	[DSN Manager]	Possibility to provide additional parameters into connection string within DSN defined in the project's DSN manager
SD-3721	[WEB MANUAL	If to use comma instead of dot as decimal separator in manual
	ENTRY]	input object, then values after decimal separator will not be
		logged in DB. It will be good if we can add a message that the wrong separator is used.
SD-3720	[DRV Manual]	Manual data logged for incorrect tag.
SD-3673	[GENERAL]	Description of the error message starts with the text
02 0010	["Connection successfully" when connection failed in PcVue
		HDS items and PcVue HDS alarms drivers.
SD-3613	[GENERAL]	In the Text field of Email Format configuration, hitting "Enter"
		for carriage returns closes the window
SD-3607	[DRV ROCKWELL PLC]	Repeated records in project DB with Rockwell PLC RT values
SD-3457	[DRV AVEVA ALMDB]	In AVEVA Historian (alarms / events) driver, filters based on
		the Alarm_InAlarm or IsAlarm fields do not work.

Summary of New Functionality and Enhancements for AVEVA Reports Release 2023 Patch 2

(compared to the original version 2023)

	Module	Description
New Features		
	[Yokogawa Data Importer]	The Yokogawa Data Importer allows importing the data out of Yokogawa recorders files into MSSQL, MySQL or Oracle database for further data analysis and reports creation.
Other Enhancements		
	[Designer Studio]	Email validation improvement.
	[Remote DEV]	Added comment on user's password change
	[Designer Studio]	TEXTBOX, Copy text after final text preparation, in some cases during web report generation can cause to an unexpected behavior
	[WEB]	Time zone consistency handling
	[LUA]	Support of LUA scripting in SQL and Step Tables
	[Communication Drivers]	Post-Script function in a driver configuration allows users to add and execute LUA script for any communication driver instance. The script will be executed after each driver instance call. That script will be applied to any values or alarms, which a driver would return to the reporting engine.
	[Security]	Project File Code Execution (CWE-22: Improper Limitation of a Pathname to a Restricted Directory ('Path Traversal'))
Comm. Drivers updates		
	[InfluxDB historical Driver]	New InfluxDB historical driver for communicating with InfluxDB cloud-based databases.
	[OPC UA drivers]	Support for HTTPS communication
	[DRV WEB MANUAL HDA]	User is now recorded into the Audit Trail, with manual data operations. Previously, NULL was recorded instead of the username.
	[DRV VTSCADA HDA ALARM]	Added support for VTSCADA 12 and higher

Corrected Issues/SCRs (AVEVA Reports 2023 Patch 2)

#SCRs	Module	Description
SD-3657	[Audit Trail]	Audit Trail, Dream Report does not record the User when
		auditing manual data entry activity is performed
SD-3658	[WEB]	If user clicks on the name of the Web Report and not on the icon,
		it shows "Generation completed with error"
SD-3660	[GENERATOR]	Generator crashes when a Footer is added to the SQL Table of
		the attached report
SD-3666	[DRV ODBC HDA	Advanced ODBC Driver - "Milliseconds From 1970" option is not
CD 2672	ITEM]	working
SD-3672	[STUDIO]	Dash character in email address causes an error message in
CD 2675	IDDV DOCKWELL	Report Settings
SD-3675	[DRV ROCKWELL INFOPLATFORN HDA]	FactoryTalk Historical values driver (SDK): no values if an item name contains @ symbol
SD-3677	[REMOTE DEV]	Driver List is empty when creating an object using remote
30-3011	[KLMOTE DEV]	development
SD-3681	[WEB]	Web Portal consumes numerous web clients of the license when
55 5001	[[[]]	used in iFrame
SD-3684	[DRV EUROTHERM	Eurotherm Data Reviewer historical messages driver unable to
	DATAREVIEWER]	read data after upgrade to 2023
SD-3685	[GENERATOR]	Error Message appears when reset Manual Data with User
		Authentication activated.
SD-3686	[WEB]	SQL Tables are resized in Web Repot
SD-3687	[RCS]	Memory leak on Remote Connectivity Service (RCS) side when
		using remote driver for historical values
SD-3689	[DRV MODBUS]	Fix for reading values defined in block/array. "Recording data in
		DR internal DB by "Record in Item Value Change" mode does not
		work when Modbus driver is used"
SD-3690	[WEB]	Leading spaces are removed from SQL query text in web report.
SD-3692	[DRV VTSCADA HDA	Fix for Designer studio crash when adding filter in VTScada Alarm
	ALARM]	Driver without choosing Column, Operator or Condition.
SD-3694	[DRV OPC UA History]	Add "GeneralCallTimeout" to OPC UA History driver to allow a
CD 2005	ICENEDATOR!	longer wait to receive the data set from OPC UA Server
SD-3695	[GENERATOR]	External expression gets N/A if text value from SQL / Step Table footer when used in expression object
SD-3697	[GENERATOR]	Exception upon generating report with SQL Table using dynamic
30-3031	[GLIVLKATOK]	row height
SD-3699	[GENERATOR]	AVC in step table does not support column tokens [c#]
SD-3700	[Audit Trail]	When administrator unlocks the locked user, this action/event is
35 3700	pridate Hatty	not captured in project audit trail.
SD-3576	[DRV PcVue WS]	PcVue Online WS Driver writes 0 values as well as causing for
02 0010	[27.17 1 0 1 0 1 0 1 1 0]	PcVue crash
SD-3703	[Web]	When user configures IIS on Win2012 server by Configure IIS
		option, it fails with an error.
SD-3696	[Web]	Wrong error message on the web portal upon attempt to login
		with a locked user.
SD-3706	[ASR object]	The [ip#unit] ("Get unit from item") feature is not supported in
		Automatic Statistical Table (AST).
SD-3707	[FT View SE Hist	FactoryTalk View SE Historical Values DB driver: if no values at the
	Driver]	first step of a Step table, other steps return no data.

SD-3702	[RA PLC RT Driver]	String and bool values are displayed incorrectly
SD-3708	[Adv. ODBC Driver]	"Empty string value" causes wrong data representation in Item Table when Adv. ODBC driver is used
SD-3711	[Web]	Autofilter in combo-box is not working for multi tag selection
SD-3712	[OSI PI AF RT Driver]	When data goes to bad quality, it causes two records with the same value to be logged.
SD-3714	[Studio]	"Search and Replace" in Tag Dictionary - extra symbols are added
SD-3715	[CSV tag values Driver]	Clicking "Connect" closes the Studio for some configurations (improper delimiter)
SD-3716	[DeltaV OPC Drivers]	DeltaV OPC HDA and DA drivers do not work properly
SD-3718	[Influx DB Driver]	Fixed support for version 1.8.10
SD-3719	[Reviewer Driver]	Fixed - No data from Reviewer Historical Values

Summary of New Functionality and Enhancements for AVEVA Reports Release 2023

(compared to the original version 2020 R2 SP1)

	Module	Description
New Features		
	[Web Clusters]	Web Cluster feature allows users to specify a report area (report cluster) with one or multiple objects, and provide a URL to that specific cluster, so that it can be published in any external web content container.
	[Report Levels]	User Authorization for report levels – in Studio configuration User Authorization for report levels - Runtime support User Authorization for report levels - Web portal support
	[Security]	New e-Signature functionality to enhance user experience for electronically signing reports: new "signed" states; location of unsigned reports; notification for reports pending for signature, changes in use of PINs
	[Security]	URL Whitelist URL – option to specify which embedded URLs in reports are approved/acceptable
	[Web]	Named Web Clients – option to reserve web client licenses for specific named users.
	[Web]	Web reports display options: for PC or Mobile. Introducing a new option to set report type.
Other Enhancements		
	[Designer Studio]	Object Tree moved from the left side to the right side of Designer Studio – improved UI for larger projects.
	[Web]	Web Portal customization - added ability to configure both custom Project Name, and custom Welcome Message, in the web portal
	[Web]	Reloading project shouldn't reset web display to a Welcome page, if report was opened through WebAPI
	[Remote Development]	Add timestamp information for revision history in concurrent development mode.
	[Security]	Following External Cyber Security Audit, security enhancements were implemented in the Web Portal.
Comm. Drivers updates		

[AVEVA Alarms ODBC]	New AVEVA Historian historical alarms ODBC driver
[AVEVA Insight OEE]	New AVEVA Insight Performance (OEE) historical data driver
[Eurotherm Reviewer Driver]	Support of SQC (SQL-based filtering) in new Reviewer driver
[OSIPI Web API]	New OSI PI web-based API historical data access driver
[BACnet Driver]	BACnet driver recompilation with new SDK v75, and removing license limitation for BACnet drivers
[Siemens Desigo CC Driver]	New Siemens Desigo CC system historical values driver, based on web REST API
Rockwell Automation PLC Real-time driver	General stability improvements and corrections in UI
Units Support	Added Units support for the following drivers: AVEVA Historian, GE Proficy Historian, Advanced ODBC driver, and in Data Models

Corrected Issues/SCRs (AVEVA Reports 2023)

#SCRs	Module	Description
SD-2664	[Web]	Timepicker does not support font modified settings in web portal
SD-3350	[Web]	If the "Filter edit box in Web" parameter is On in SQL table, the
		last row of the table does not show up.
SD-3483	[Web]	Some of the web themes result in no color indication on the e-
CD 2542	[CDC Modulo]	Sig "Pencil" icon tell if signed or unsigned. Memory look and exception while report generation with SDC
SD-3542	[SPC Module]	Memory leak and exception while report generation with SPC histogram object when histogram is based on array of the same values.
SD-3543	[e-Signature]	Report opened in PDF can't be e-signed, but it is marked as signed in the Web portal
SD-3545	[Web Chart]	Web Chart display incorrect values (rounded to integer) on
CD 2550	[C]]	tooltips and on grid on Y axis for negative values.
SD-3550	[General]	CSV and XML targets are not supported for report generation from command line
SD-3551	[Web]	Disabling Report History in Project Settings - Web portal, does
		not work properly
SD-3554	[Batch]	Dynamic generation on Absolute Batch ID fails from web portal
SD-3555	[AST object]	AST with vertical orientation populates value inside the Excel
CD 2561	FL IN 41	template in a wrong way
SD-3561	[UM]	A user who is a part of a Windows user group with admin rights, doesn't get admin privilege
SD-3562	[Web]	Reloading reports resets Web Portal to a Welcome Page
SD-3564	[General]	Improved stability in the report generations. Unexpected
		behavior of Generator process.
SD-3572	[Web]	Folder management (Report Levels) in Web is not working properly, while report's generation it jumps to parent folder from selected subfolder
SD-3586	[RA FT DRV]	Browse of tags failed using FTSQL driver when type of the column TagName is varchar(255) in the DB.
SD-3588	[Web]	Error message - Missing JWT Token in Authentication HTTP Header pops up after login in Web E-signature page.
SD-3589	[Web]	Draw tables loose alignment in Web Report
SD-3592	[Adv. ODBC Alarms DRV]	Advanced ODBC Alarms driver with Custom Property with Reserved Name in SQL (User)
SD-3594	[Rem. Dev.]	User Locked status is not available in Remote Dev Mode
SD-3595	[Step Table]	Column type Row Index can`t be changed in a Step Table
SD-3597	[AVEVA\Wonderware Hist. DRV]	SQC in Batch Definitions does not work if batches are defined by data item selected from AVEVA\Wonderware Historian driver.
SD-3598	[Studio]	Dream Report crashes when right click on report free area of designer
SD-3600	[Alarm Table]	Alarm Display Filters are not applied in some Alarm Tables
SD-3601	[DBatch]	DBatch stops to write process values when batch id exceeds 32767 and SQL server or MySQL is used as project database
SD-3602	[RA FT View SE Hist. Values DB DRV]	Driver FactoryTalk View SE Historical Values DB returns wrong result for statistical function Running Time when no advanced SQL condition is used

SD-3603	[RA FT View SE Hist. Values DB DRV]	Driver "FactoryTalk View SE Historical Values DB" incorrectly handles requests with advanced SQL condition when condition tag contains "/" character, for example: //::[PLC1]Train_41_Actual_Step
SD-3604	[Web]	Web portal is not working properly when using chromium with too many reports in the project
SD-3605	[Studio]	DR Studio crashes upon adding alarms filter from FTView SE Historical Alarms, when there's no connection to FTView
SD-3606	[Web]	Web objects are not working properly when the SQL Table has no headers
SD-3608	[OPC UA RT DRV]	OPC UA RT values driver: Test connection fails because certificate file cannot be copied
SD-3609	[SPC Module]	Incorrect configuration of SPC can lead to abnormal memory usage and generation exception.
SD-3611	[OSI PI AF DRV]	No tags browse in OSI PI Asset Framework driver
SD-3614	[AVEVA Hist. SDK (AE) DRV]	AVEVA Historian SDK (alarms/events) driver requires more waiting time to establish connection to the server.
SD-3615, SD-3418	[E-Signature]	In E-Signature configuration, text font option is not working properly
SD-3616	[General]	When SQL table receives data of type DATETIME with TIME part filled only it can lead to exception during report generation
SD-3618	[E-Signature]	E-signature page displays incorrectly (overlapped rows)
SD-3619	[Alarm Table]	Custom Alarm filter based on Custom Property with Reserved Name in SQL (User) doesn't work. Alarm table brings N/A.
SD-3620	[RCS]	Generation on event from Remote driver fails
SD-3624	[OPC UA RT DRV]	Data aren't logged in DR DB from ADISRA OPC UA real time Server.
SD-3625	[OPC UA RT DRV]	SDO brings "err" using current value from ADISRA OPC UA real time Server for some tags.
SD-3628	[RA PLC DRV]	Generator crashes in the project with multiple write-backs to Rockwell PLC's
SD-3631	[General]	Arabic font is garbled in PDF
SD-3632	[SPC Module]	SPC Nelson Rules Calculation fails if use dynamic TagName for SPC Configuration
SD-3634	[Web]	It appears that the "Default" report instance is generated when generating a report from the Portal home page, regardless of which instance is being generated (generated by clicking the new report generation icon).
SD-3635	[Web]	Drawn objects are shifted in Web Report
SD-3636	[Adv. ODBC HDA DRV]	Wrong query for getting previous value in the Advanced ODBC Historical Values driver
SD-3637	[Web]	Option "Dynamic row height" doesn't work in web report
SD-3638	[SQL Table]	"Open Sans" font is garbled in SQL Table in PDF.
SD-3639	[Eurotherm Reviewer DRV]	Generator crashes upon generation of the alarms report from Eurotherm Reviewer when specific set of uhh files used
SD-3640	[OPC UA RT DRV]	Write-back doesn`t work with Kepware OPC-UA
SD-3641	[Logger]	Trigger tag is recorded with another timestamp, comparing to the other tags of the group

Corrected Issues/SCRs (AVEVA Reports 2020 R2 SP1)

#SCRs	Module	Description
		Eurotherm Review driver is using an old mdb ODBC driver. Some
	15 d DD) (1	SQL expressions are not supported in the old ODBC driver. New
	[Eurotherm DRV] [FT HDA VALUES	ODBC driver for *.mdb, *.accdb databases to be used.
	AND ALARMS DRV]	Timestamp format in SQL queries was changed due to customer request.
	[SECURITY]	AVEVA Security Audit
	[SECORITY]	RTM Service is installed with Local System account but has to be
	[SECURITY]	installed with Virtual Service Account
	[SECURITY]	Digital signature is added to exe and dlls
	[SECURITY]	Files in System folder can be changed by non admins
		Syncfusion Dashboard service is installed with Local System
	[SECURITY]	account
		AVEVA Historian Historical Values Driver: Ability to select a
		column to be used for Quality value, ability to specify which
	[AVEVA DRV]	values to be considered as good and ability to include NULL values into result set
	[LICENSE]	AVEVA license check can fail after some undefined time interval
	[LICLIVOL]	Tuning parameter "UsePrevPointForFirstStep" has to be disabled
	[GENERAL]	by default
SD-3203	[SPC]	Out of memory crash fixed.
		Dream Report log wrong values in internal DB using Modbus
SD-3408	[Modbus]	driver.
CD 2425	IDAD CDADIII	In the Bar Graph, data displays are being overlapped by the
SD-3425 SD-3485	[BAR GRAPH]	adjacent bar in a group
SD-3486	[CIAT] [BATCH]	DR_CAIT process is not restarted with reload of DR project. Batch definition based on Custom View doesn't work.
3D-3400	[BATCH]	Adding tags to the logger studio from Micro Logix PLC causes to
SD-3490	[Rockwell PLC]	the DR studio hang.
SD-3491	[Modbus]	Issues with report generation on event from Modbus PLC
		Generation on event based on tags from InduSoft real time driver
SD-3495	[InduSoft DRV]	doesn't work if DR project was started before Indusoft project
		Japanese and Chinese symbols are garbled in the Driver Manager
SD-3500	[Driver Manager UI]	dialog
SD-3503	[GENERAL]	Spelling mistake in the "Value Range Indicator" Object Configuration.
30-3303	[GLNLINAL]	Support of operator NOT LIKE in the definition the alarm filter of
SD-3512	[Eurotherm DRV]	the Eurotherm Data Reviewer historical alarms/events driver
SD-3515	[STAT. FUNC]	Counter calculation in ADF should include the end of the period.
		DR Logger does not log values on Absolute Time if data source is
SD-3517	[Analytics DRV]	Data Model
		In DRWeb portal, Step table and Item tables will plot in different
CD 2510	[\A/ED]	sizes even if they have exactly the same formatting in every
SD-3519	[WEB]	aspect AVEVA InTouch (historical alarms / events in ALG files) driver,
SD-3520	[INTOUCH ALG DRV]	Custom filters do not work
SD-3521	[CSV DRV]	Number of tags that can be imported from a single file is limited
	1	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2

SD-3522	[INTOUCH LGH DRV]	End time of the step is included in the calculation based on LGH driver data
SD-3523	[INTOUCH ALG DRV]	No data from ALG Alarms driver on particular OS.
SD-3524	[MX DRV]	ArchestrA embedded objects are not supported in hierarchical mode of MX Driver for more than 2 levels
SD-3526	[ALARMS]	Wrong calculation of the alarms duration when every alarm is counted once

<u>Summary of New Functionality and Enhancements for AVEVA</u> <u>Reports Release 2020 R2</u>

(compared to the original version 5.0 R20-3)

	Module	Description
New Features		
	Notifier	New notification module. This module allows message exchange between users accessing the project at runtime. User can send messages with link to problematic reports directly from the Web portal.
	Values Quality Management	Support of Value Quality when representing the data in objects like Chart, Item Table and Step Table. List of drivers that support Values quality can be found in the Help.
	Statistical Functions	New Alarm related stat functions for ISA 18.2 compliance. Refer to the Help documentation.
	New Eurotherm Reviewer Comm. Drivers	Added new Reviewer Eurotherm drivers HDA Item, HDA Alarms, Batch Monitor
Other Enhancements		
Other Limancements		
	Web	Combo box to filter report list by user rights
	AST	Added support of Nelson Rules statistical functions to Automatic Statistical Table object
	Web	Added support of X-Y mode in Web interactive Line Chart
	SQL Table	Advanced data representation in SQL table as with Item Table and Alarm Table using Lua HDA driver
	Project Audit Trail	Audit Trail – logs for communications errors from drivers AVEVA drivers, GE drivers, Rockwell Automation drivers, OSI PI drivers and OPC drivers
Comm. Drivers updates		
	OPC UA Real-time	General stability improvements
	Rockwell Automation PLC Real-time driver	General stability improvements and corrections in UI
	Units Support	Added Units support for the following drivers: AVEVA Historian, GE Proficy Historian, Advanced ODBC driver, and in Data Models

Corrected Issues/SCRs (AVEVA Reports Release 2020 R2)

#SCRs	Module	Description
SD-3409	Web User Management	When report is generated using an action button from a different web report, the User Management settings are ignored.
SD-3419	Comm. Drivers	WW Alarm DB Logger (historical alarms/events database) driver. Alarm records are not combined correctly.
SD-3423	General	Improved memory management when retrieving data from DR internal history
SD-3426	Comm. Drivers	Added new filtering option "QualityDetail" in AVEVA Historian Driver
SD-3429	Comm. Drivers	AVEVA InSight driver: Test connection returns "Basic authorization failed" error if password includes "\" symbol.
SD-3431	Comm. Drivers	WW Historian Driver: Duplicate tag names in Combo Box
SD-3432	Runtime	Generator crashes on start of the project, if tag for event-based generation comes from PLC that is disconnected
SD-3433	Web Interactive Chart	Option to set the precision on tooltips in Chart.
SD-3435	SPC Module	Dynamic objects from report aren't considered in calculation of correction factor in SPC configuration.
SD-3436	Web Portal	URL for report generation opens up a Welcome Page of DR Web
SD-3438	AVEVA Alarms Historian	In AVEVA Historian (alarms / events) driver, filters using the "Alarm_DurationMs" field does not work.
SD-3441	Comm. Driver	Fails to connect to a PLC through OPC-UA
SD-2824	Comm. Driver – OPC UA	Unable to connect to OPC UA Kepware server in encryption mode.
DEV-360	Web Portal	Web action button login and logout are not working
DEV-362	Web Portal	Support of placeholder %hostname% in text hyperlink object

Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R20-3

(compared to the original version 5.0 R20-2)

	Module	Description
Other Enhancements		
	Communication Drivers	Added new communication driver for Rockwell Automation PLC's
	Dashboards	Special report for Dashboard calculations to be created without scheduler settings
	Remote Connector	Added support for writeback to the real time tags
	Licensing	Removed limitations for Eurotherm drivers from the license provided in archestra.lic, (not in Dream_Report_WW)!
	Licensing	Added Dashboards Option in DR for AVEVA License
	Communication Drivers	OPC DA - Added possibility to change Update Rate parameter from configuration dialog in OPC DA driver.

Corrected Issues/SCRs (Dream Report 5.0 R20-3)

#SCRs	Module	Description
SD-3212	Communication Driver	CSV Driver - Add ability to select tags and force them to be string tags
SD-3369	SQL Table	Link in SQL Table does not work if the text of hyperlink contains more than 16 characters
SD-3381	Communication Driver	Memory leaks issue in Wonderware Historian Alarm driver
SD-3382	Communication Driver	Wonderware Historian Alarm driver fix for alarm filters reset issue
SD-3396	Remote Connector	Added support for writeback to the real time tags
SD-3407	Communication Driver	FactoryTalk View SE Historical Values DB driver does not return result when it is used in a Step Table and there is no data in FT DB for the period of a table
DEV-360	WEB	"Time in UTC format" option is ignored in Batch Definition, defined in External DB
	Designer Studio	Bar Graph Undo/Redo issue
	Dynamic Token	Improved behavior of d# token

Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R20-2

(compared to the original version 5.0 R20-1)

	Module	Description
New Features		
	Preconfigured Object's Panel – Designer Studio	New Panel with preconfigured object settings will allow user to select object with preconfigured settings.
	User Management	Added new options to manage enhanced access rights for the users in the Dream Report Dev. and in the Web
	Web Portal	New option that will allow operator to email generated report from the Web portal
	Statistical Functions	SPC Nelson rules violation statistical function
Other Enhancements		
Other Elmancements	Advanced Visualization	AVC in Step and Free SQL tables supports values taken from other columns
	Advanced Visualization	Support of AVC in the Dynamic Web Chart set to interactive mode (create AVC info for DML)
	Report Settings	Added number of copies that will be sent to printer once report is generated
	Communication Drivers	Export/Import of driver definition instances to/from XML. This will allow user to transfer driver definition from one project to another.
	Expression Object	Use 0 as result in Item Field, Expression, Compound if the calculated result returned as NA
	Chart Object	Improved formatting of numbers on Y axis in chart without trailing zeros
	Report Settings	Added option for emailing of CSV and XML reports in email body
	Web Elements	"DateTime" pickers now uses project settings to show configured date time format and week start
	Custom Script Objects	Added two new Custom Script Objects: "SectorPie" and "SectorDoughnut"
	Step Table	Added option to configure step correction to manage step start and end times
	Item Table	Added decimal precision support to the Item Table object
	Web Elements	Added new "Reset Manual Input" option into configuration of Submit Action Button.
	Designer Studio	Implemented save/load custom units to/from INI file
	Excel	Improved stability of Export to Excel option
	License Information	Enhanced license information in Designer Studio to show license details even in case of an invalid license

Comm. Drivers updates		
	PcVue Web Services	Redundancy support in PcVue driver
	OPC UA HDA	Improved OPC UA HDA driver, support of certificates and user authentication
	OPC UA DA	Improved OPC UA DA (real-time) driver, support of certificates and user authentication

Corrected Issues/SCRs (Dream Report 5.0 R20-2)

#SCRs	Module	Description
SD-3338	DR Studio	DR Studio crashes upon creating Pivot Group based on Free Table
SD-3347	Communication Driver	SQC stopped working in Review HDA driver
SD-3348	Communication Driver	Locale is changed in DR project, when iFix driver is in use
SD-3332	Communication Driver	In Wonderware Historian driver, the "Filter out Quality 133" parameter does not work for statistical functions
SD-3366	Draw Table	Objects lose size when copying content of the Draw Table from empty cells into report working Area
SD-3363	Communication Driver	Test Connection to OSI Asset Framework fails when user name contains domain part domain\user
SD-3362	Batch Definition	"Time in UTC format" option is ignored in Batch Definition, defined in External DB
SD-3364	Communication Driver	A possibility to disable msec in IWS/InTouch Edge HMI External History Driver
SD-3352	Communication Driver	Rockwell RSView 32 driver (DBF). Error message when closing Communication Configuration Wizard, even if the test is OK
SD-3373	Licensing	Extra tags are added to the license count when retrieving BatchID defined in external DB
	Dynamic Report Generator	DRG does not bring the list of batch ids for batches that are based on "Batch time" definition when batch is defined on the item from a data model
	Communication Driver	Geo SCADA Expert historical events and alarms: timestamp of events and alarms does not correspond to local time (but corresponds to UTC)
	e-Signature	If user has no e-signature definition, he is still allowed to sign report. This has been restricted.

Summary of the New Functionality and Enhancements for Dream Report Release 5.0 R20-1

(compared to the original version 5.0 R19-3)

	Module	Description
New Features		
	Communication Driver	OPC UA HDA Driver has been added. It supports encryption and security certificates.
	Chart	Implemented support of Logarithmic Scale for Chart based on LOG on base 10
	Report Data Server	Redesign of RDS engine in term of report generations
	Report Data Server	Added new HDA part for System Driver. This driver provides access to historical values of tags defined in data models.
Minor Improvements		
willor improvements	Dynamic Tokens	Added possibility to use [f#] dynamic tokens in table headers for alarm, item, step vertical, step horizontal, SQL non-grouped, SQL-grouped tables.
		Note: It will work on Force Object Update action from the web for the following tables: Alarm, Item, Step vertical, SQL non-grouped.
	Audit Trail	Added remote development operations tracking into Audit Trail
	Table objects	Added ability to vertically align text inside Simple Draw Table and SQL Table
	Remote Development	New parameter for remote project session reconnects timeout: <module name="ConcurrentDev"></module>
	Custom Objects	Add a button to open dynamic token selection dialog to select a token that can be used in Custom Content configuration
	Chart Object	Chart reference lines enhancements
	Web Tree Object	Context search filter implemented
	Web Combo Box Object	Add Web Content objects to the list of "Select Objects for the Update" in Combo Box definition.
	License	Change subscription license upgrade to use specific subscription end time
Comm. Drivers updates		
	Communication Driver	Implemented possibility to select tables in FTView SQL HDA ITEM driver

Communication Driver	Added Time zone parameter into configuration of GE Historian driver

Corrected Issues/SCRs (Dream Report 5.0 R20-1)

#SCRs	Module	Description
SD-3269	Batch Definition	Batch list is not updated properly when batch def list received as list of report instances from another combo. See attached project
SD-3271	Communication Driver	Modbus driver items defined in block are not updated correct in unsolicited mode.
SD-3275	Excel Module	A possibility to import data from Excel file with the separate columns for date and time
SD-3276	Communication Driver	StoppedBy field can`t be retrieved from BatchDetails table of Review
SD-3272	Communication Driver	Not possible to use a Group column as a filtering condition in Yokogawa Alarms driver
SD-3280	Communication Driver	TView driver: file explorer doesn't display files.
SD-3279	Communication Driver	Logger crashes upon reload of the project, where MX driver is used
SD-3281	Communication Driver	Increase the number of characters allowed to be presented as a result of SQL Query
SD-3283	Communication Driver	Wrong timestamps retrieved from FT Historian using InfoPlatform drivers
SD-3288	Logger	Data logging stops shortly, when 2 log groups from Siemens S7 are recording frequently
SD-3284	Communication Driver	Report Generation fails to be triggered from ITME
SD-3295	Communication Driver	Generator crashes with WW Historian Alarms driver
SD-3297	Communication Driver	Slow shutdown when using WW Historian driver
SD-3298	WEB	Web Report shows Generation Error as soon as custom object SQL based Bar contains a query that brings empty result set
SD-3308	Chart	Chart shows incorrect timestamps for data when data is requested from Review during DST time change to Winter Time
SD-3306	Communication Driver	PcVue HDS Items Driver doesn't support string values.

<u>Summary of the New Functionality and Enhancements for</u> <u>Dream Report Release 5.0 R19-3</u>

(compared to the original version 5.0 R2)

	Module	Description
New Features		
	External web content	External web content object enables to insert and use a web page or external documents in reports. Such external content may be a web page or a document (PDF or plain text).
	Communication Driver	Rockwell Automation FactoryTalk real-time values driver
	Communication Driver	Rockwell Automation FTAE database new driver for historical alarms and events
	Communication Driver	Rockwell Automation FactoryTalk historical alarms and events via Rockwell Automation Info Platform
	Communication Driver	Siemens S7 driver has been completely redesigned and support for 1200 and 1500 series has been added.
Minor Improvements		
	SPC	SPC configuration export/import xml file will allow user create SPC definition our of Dream Report project and apply it to the project or transfer the definition between projects.
	GENERAL	Starting from version 5.0 R19-3 Dream Report will have new versioning approach: Where 5.0 – is major DR version, R19-3 correspond to 3 rd release in 2019. Added new string into Help About dialog that will show this information.
	Advance Visualization	Added support of dynamic tokens in the item field widget color ranges
	Scrip Object	Added new property type for script object to hold multiline strings
	Multi Tag Aggregation	Currently, when editing an MTE, if you click <enter> to go to a new line, it closes the MTE tool. If trying to create a multi-line expression, this is a problem.</enter>
	Report Data Server	New System Tags: Number of Reports in the project, Number of Reports in the generation queue
Important Notes		
		Starting from product version 5.0 R19-3 the Database Archiving feature had been removed from the product
		Dynamic Dashboards version upgrade
Driver security updates		
	Communication Driver	In case of connection failure, the message will contain user and password information in ODBC Historical Alarms/Values driver

Communication	Driver connecting string contain user and
Driver	password information in "FactoryTalk View SE
	Historical Alarms and Events DB"

NOTE: (For more details, please, refer to the Dream Report® Help documentation)

Corrected Issues/SCRs (Dream Report 5.0 R19-3)

#SCRs	Module	Description
SD-3240	Communication Driver	Communication Configuration Wizard display in the description field for OSI Soft PI Asset Framework historical values driver that it is real- time values driver
SD-3242	Web Elements	Replacement of time period is not working from Action button when start and end of period taken from expression objects.
SD-3245	DBatch	If at least one process value is missing in one of the batches recorded by DBatch all step table will show NA's
SD-3246	Report Generator	Generator crashes when ADF is applied, based on 1 last value per day, sample-based
SD-3247	Batch Definition	When "Custom View" is used for the batch definition, every time Batch definition dialog is opened all columns for that batch will be reset.
SD-3248	Web Elements	Time Picker is not available with web interactive Pie Graph
SD-3249	Batch Management	Batch end time is not calculated correctly when external database source and SQC in Batch definition are used
SD-3257	Web Manual driver	Web Manual input with the option "Current Time" must take the time of submit action
SD-3258	Communication Driver	Browse issue with OPC-UA server (the list is not complete)
SD-3260	WEB	Update object request does not pass User name into Generator. It's not possible to retrieve User name in the expression object with help of LUA function in this case
DEV-225	Advance Visualization	Wrong AVC results in chart when digital data is used (0 1) Wrong AVC results in Value Range Indicator script object when digital data is used (0 1)
DEV-231	Designer Studio	Report Settings Dialog - Changes made through the panel are not saved
DEV-237	RMC	RMC does not refresh list of reports when report is renamed in Studio and Refresh Reports is pressed
DEV-238	CHART	Chart doesn't display vertical lines when chart based on SQL query. Simulation project attached.
DEV-244	GENERAL	Display the total number of available web clients in Help About (Studio/RMC)
DEV-247	Communication Driver	Added check for data model name, so it cannot be the same as data source name and an opposite!

<u>Summary of the New Functionality and Enhancements for</u> <u>Dream Report Release 5.0 R2</u>

(compared to the original version 4.83)

• Electronic signature in the web portal

Authorized users now can electronically sign reports from the DRWeb portal. This feature was developed in addition to the standalone e-Signature Console.

• New report output format - XML report files

A new user-configurable XML output format allows users to build reports to comply with XML submission requirements of water quality reports.

• Script Object with objects library

Using LUA scripting, users can build their own graphical objects for reports – e.g., a circular chart object, status displays, etc.

• **New Script-based Graphical Objects** (based on script object library) Gantt chart, new gauges, and other graphical objects and shapes.

Powerful BI Dashboards

Create, share, and manage dashboards through user-friendly interfaces, and connect your dashboards to all your Industrial <u>and</u> Business data sources.

Note: This feature has limited availability for certain OEM's

• Object-independent Updates in Web Portal

Faster updates of web reports, with uninterrupted web page refreshes.

Chart reference lines

Option to add Vertical and Horizontal reference lines based on preset or dynamic criteria/limits.

For the Web Interactive Chart, the new interactive cursors will allow highlighting of a selected area of data points on line charts.

• Batch Manager enhancements

Ability to use advanced SQL conditions, use DSN-less database connections, and improved user interface.

Report Data Server (RDS)

Dream Report becomes an "information platform" for external systems. Expose Dream Report's powerful data aggregation and calculation engine to other HMI's, web portals, custom applications, etc.

OPC DA Server for RDS

A new Dream Report OPC Server exposes the Analytic Data Server. The OPC Server exposes the project's data to external third-party tools as a real-time OPC data source.

Cost Calculation Module

The Cost module allows users to define rates and tariffs (i.e., methods and definitions calculation of Cost), and use the results of those calculations in the reports. It has support for Energy Tariffs & Billing rates/schedules for utilities billing reports.

New options in "Counter" statistical function

The "Counter" statistical function has been enhanced to allow the user to specify the "totalizer" direction (increasing/decreasing counter), as well as new options for counter calculations, including simple difference (last value minus first value), up-

counter, down-counter or automatic mode. Additionally, if Cost calculations have been defined, a Cost definition can be associated with the Counter calculation.

• "Difference" Statistical function in Bar object

The "Difference" statistical function is now available in the Bar Graph object. This is useful for production counters and utility meter displays over various time intervals.

• Dynamic Alarm Filters and Filter Selection from the web

New option in the Web Combo box – "List of Alarm Filters". This enables users to select predefined alarm filters in ad hoc reports on alarms and events.

• New Alarm Statistical functions (in Single Data Object, Bar Graph, ...)

New statistical functions for alarms statistics calculations in several data objects - Maximum duration, minimum duration, maximum response time, minimum response time.

Optional In-memory Calculation of Step Commands

The Step Table object can enable "in-memory calculation" option in, which provides significant improvement in generation performance of the Step Table where this option is selected. Please note that this option will impact available memory, so should be used with a reasonable amount of data.

• Freemium License

Free for distributors, 10-tag Dream Report permanent license available.

Subscription License Model

Dream Report version 5 supports both permanent and annual subscription licensing. For more details please contact your sales representative.

• AVC (Advanced Visualization Condition) Manager

The Advanced Visualization Condition manager is a tool for creating and storing advanced visualization condition definitions, that can be later used in single data item, Automatic statistical table, Step table and SQL table.

• TDM (Time Definition Manager)

The Time Definition manager is a tool for creating and storing time definitions for quicker use in creating reports.

• Search Objects Feature:

New search options added to the reports tree and to the "add dynamic token" screen. Write text in the search box and the list will be highlighted.

• Chart enhancements:

- 1. UI enhancement: In data definition tab, move the line up or down in the hierarchy.
- 2. In the Appearance tab, two new options added:
 - a. Format Real or Scientific
 - b. Precision.

• Test connection to the mail server:

A new button is added to the Report Settings – Email Configuration: "Send Test Mail". This button will help user to ensure that the email settings correctly entered.

• New quick info panel – Report Settings (left side of the screen):

The Dream Report studio has a new panel – "Quick Info Panel". In this panel user can find the reports list and get quick access to the report settings - time definition, scheduling and format settings.

• Alternative destination folders for report Instances:

In "Report settings" in "General" tab, when the "copy report files to folder" option is checked, uncheck the "apply to all" option to pick the report instances and copy them to a different folder.

• FTP Upload Enhancement:

If the FTP upload is selected, user can check the "active mode" option if the FTP server requires "Active Mode" for the connection.

• Data Model Configuration Enhancement:

Two new properties are added for the data model definition – **Description** of the Virtual Tag and **Units**

• Widget Configuration Enhancement:

In the Widget configuration by double click on the Minimum or Maximum limits. User will be able to add Dynamic Token as the limits from the list of objects available in the report.

Custom object library:

The custom object library has new set of objects in the list.

Note: It is known that if user is planning to use custom object as part of Pivot group its wont work as any other standard Dream Report object. This limitation is planned to be resolved in the next version release.

NOTE: (For more details, please, refer to the Dream Report® Help documentation)

Driver Enhancements

New Advanced ODBC Alarm driver

Extracting alarms from 3rd party databases using simple mapping with dynamic parameters list and alarm filters.

New System Driver

Exposes "system health" parameters for reporting.

• New Rockwell Driver

The Rockwell "FactoryTalk View InfoPlatform Historical Values" connects to the FactoryTalk View product of Rockwell.

• Proficy Historian Alarm Driver Performance Enhancement

Improved driver for GE Historian historical alarms extraction.

• IntelaTrac Driver Enhancement

Exposes data collected from nested/conditional rounds in IntelaTrac.

WWALM Driver Enhancement for alarms/events

Ability to configure extraction of alarms and/or events separately, resulting in faster query times.

Updated Communication Driver Names

The descriptive names of several communication drivers have been updated to better reflect the current product names/functionality with which they work

• Tag values in CSV files Driver Enhancement:

New button added to the configuration – "Item name rules": User will be able to remove or replace certain characters in the tag name.

• InTouch Edge / InduSoft Driver Enhancement:

New option added – Ability to communicate through encrypted port and possibility to retrieve the historical date with UTC based timestamps.

NOTE: (For more details, please, refer to the Dream Report® Help documentation)

Corrected Issues/SCRs (compared to the previous version 4.83)

SCR#	Module	Description
SD-3233	[GENERATOR]	A value of the report object cannot be used in the report file name.
		It displays 0 instead of the object value
SD-3232	[Web Portal]	When pressing on "Refresh" Button in the "Web Trend" Report error occurs.
SD-3231	[GENERATOR]	Generator exits immediately after project start with error message in RTM log "exit on crash" on windows 7
SD-3230	[Cost Module]	Wrong calculation result using Cost module
SD-3227	[InduSoft]	Advanced SQL Condition doesn't work with Indusoft Historical Values driver, using mapped item names.
SD-3226	[InduSoft]	Indusoft wizard add Indusoft legacy drivers to the project. See description.
SD-3224	[GENERATOR]	Tuning parameter from ODS.System.config TimePeriodIncludeEnd is not considered in calculations using Advanced ODBC driver with option timestamps in SEC FROM 01.01.1970
SD-3222	[Adv. ODBC Driver]	Hierarchy tag browse doesn't work in the Advanced ODBC driver
SD-3221	[Citect Historian DRV]	A possibility to configure the number of days back, to search for the previous point for Citect Historian driver
SD-3219	[SQL Table]	SQL Tables Footer are not available in Analytical Driver
SD-3217	[Web Portal]	Time picker displays selected date in a default format, ignoring Localization settings of the project
SD-3209	[Web Portal]	Generate PDF" button doesn`t work with HTTPS protocol
SD-3207	[OPC HDA DRV]	Some stat. functions don't work with OPC HDA Boolean values
SD-3203	[SPC Module]	Exception while generation of SPC object when data source return only one value in time period.
SD-3202	[Web Report]	Zoom issue for Web reports if in the project iFix drivers was used.
SD-3200	[GENERATOR]	CSV reports are not copied upon report generation
SD-3199	[GENERATOR]	Report is generated on event from iFix upon project reload
SD-3197	[Citect Historian DRV]	No items browse in the multi-cluster Citect project
SD-3194	[InTouch ALG DRV]	Some events are missed in the Alarms Table from the InTouch ALG files
SD-3193	[Yokogawa Hist. DRV]	Some "*.gse" Yokogawa files cause crash of DR modules (Studio, Logger, Generator)
SD-3192	[Excel Driver]	DR fails to export all data from xlsx file
SD-3191	[GENERATOR]	MX Event-based report is generated upon reload of the project
SD-3190	[GENERATOR]	Boolean values False and True displayed as 0 in SQL table using query to GE iHistorian.
SD-3189	[IntelaTrack DRV]	Query text to IntelaTrack should be changed
SD-3188	[Batch Manager]	Wrong batch data from DRG when Batch is defined in external DB
SD-3187	[Review DRV]	End of the period is included in the request from Review values driver
SD-3184	[CSV Realtime DRV]	Duplicated records logged into the database using CSV real time values driver. Simulation project attached.

SD-3183	[Web Portal]	Combo Box doesn't display the tag list from UHH direct driver, if a report object retrieves data from the same source
SD-3182	[DBatch]	DBatch fails to connect to the remote SQL Server
SD-3175	[WinCC HDA]	Slow performance of the WinCC Alarms driver.
SD-3173	[OPC UA]	No browse of items from Yokogawa OPC UA server.
SD-3169	[GENERATOR]	User that was added from Windows Active Directory and the name of the
		user includes capital letters doesn't see unsigned reports in e-signature
		console.
SD-3168	[GENERATOR]	Generator crashes when step of the Step table is batch-based
SD-3161	[OPC UA]	OPC-UA driver issues. Updated.
SD-3158	[DRV INSQL HDA	Forward slash symbol is not treated well with WW Historian summary tags
	ITEM]	
SD-3151	[YOKOGAWA]	No Batch data from Yokogawa files
SD-3150	[DRV PCVUE HDA	DR Studio crashes with PcVue HDS Alarms driver
	ALARM]	
SD-3149	[Citect VJH]	Alarm filter doesn't work if Alarm Text column doesn't contain any values.
SD-3147	[Batch Manager]	"Days back" option of the Batch Def. is not applied in DRG. Minor Batch
		Definition Improvements. Now if setting "days back" to 0 it shows all
CD 2444	[C	batches.
SD-3141	[Generator]	Error messages in the log file about "failed attempt to copy non-existing
		report file targets". If you have only PDF, you get an error about XLS and CSV files.
SD-3139	[OPC UA RT]	Norwegian symbols are garbled with OPC-UA driver.
SD-3137	[Chart]	The line in chart is not displayed if advanced visualization is specified in
02 0101	[Chart]	the chart, and the values for chart line out of range of specified limits.
SD-3129	[Report Setting]	If remove Daily or Weekly Report generation schedule, and reopen Studio,
		then new timestamp 02:00:00 will be added to "Daily or Weekly Report"
		generation schedule
SD-3126	[InduSoft]	DR Studio crashes upon modifying Communication Drivers dialog.
SD-3123	[Generator]	In a Hot Backup mode, user can generate reports manually from RMC and
		Web Portal, but cannot use Action Button "Generate Report"
SD-3122	[GENERATOR]	XLSM not copied to a second location specified in the report settings
SD-3114	[S7TCP Rtltem]	Record on event from Siemens S7 is not functional.
SD-3109	[STATLIB]	Stat function "Difference" returns N/A with some types of values.
SD-3108	[OPC RtAlarm]	Logger crashes upon alarm from OPC AE update.
SD-3105	[YTPCVueHDA]	Generation on event from PcVue Web Services doesn't work
SD-3102	[CSV Alarms]	CSV Alarm driver doesn't transfer the data into Dream Report database
SD-3091	[STF]	Logged Value Counter has no result
SD-3089	[DRV WWMX RT ITEM]	Generator crashes upon start of the project
SD-3085	[DRV ODBC HDA	Average value can't be retrieved using Advanced ODBC driver
SD-3077	[LICENSE]	Free web client is not recognized by web portal
SD-3077	[EXCEL]	Excel report cannot be printed
SD-3072	[GENERATOR]	If an Expression containing other elements of a table Footer was created
35-3010	[OLIVLIATOR]	before these elements, it is not possible to retrieve these elements' values
		in the report.

SD-3066	[GENERATOR]	An object which gets a footer value from a Step Table, is not calculated when used in another report	
SD-3058	[DATASERVERHDA]	Setpoint Analyses functions do not work based on Data Models	
SD-3049	[OPC DA]	Option to set the reconnection period if the connection fails for OPC DA driver.	
	[OTHER]	VRI (Virtual Report Instance) definition export to CSV now can be exported with a header line. General refactoring/enhancements for VRI import and export to CSV done.	
	[Report Settings]	Missing button "Add" in <i>Select Data Item</i> group in "Report Name Format" tab	
	[XLS Export]	Log messages with LEVEL_NORMAL level and ERROR_MSG message type	
	[STATLIB]	Calculate "diff" for different types of VARIANT. Previously, it was calculating for VT_R8 only	

System Requirements

Hardware Minimum Requirements

• CPU: Dual Core 2.4 GHz+

• RAM: 8 Gb+

• HDD: 2 Gb (for installation) minimum, 7200 rpm or higher (or SSD)

Video adapter: Minimum memory 128 Mb
 Network adapter: No special requirements

• Monitor resolution: 1920x1080

Hardware Recommended Requirements

For medium sized licenses of Dream Report (250, 1000, 5000) ODS recommends the following HW configuration:

• **CPU**: 4 Cores i7 CPU with Hyperthreading support.

• RAM: 16 GB of RAM. However, if user is planning to have above 5 Web clients in the license, Dashboard feature in active use and take advantage of product data logging, then 32 GB will be more appropriate fit.

• HDD: 1 TB SSD or above

Video adapter: Minimum memory 128 Mb
 Network adapter: No special requirements

• Monitor resolution: 1920x1080

Operating Systems Supported

- Windows Server 2012 (incl. R2), any SP, (32-bit and 64-bit editions)
- Windows 8.1 Professional and Enterprise
- Windows 10
- Windows 10 for IoT
- Windows Server 2016
- Windows Server 2019
- Windows 11
- Windows Server 2022

<u>Important NOTE: With Windows 2012 users will have to install Chrome Web browser as IE 10 is</u> no longer supported.

Databases Supported

- MS SQL Server 2005, 2008, 2012, 2014, 2016, 2017, 2019 and 2022 Express, Standard and Enterprise (using ODBC SQL Native Client 11)
- MS Access 2000, 2003, 2007, 2010, 2013, 2016, 2019
- MySQL 4.x and 5.x versions over ODBC driver 3.51, 5.1
- Oracle 11, 12 over Oracle XE ODBC driver

Validated Web Browsers Support for Web Portal

- Chrome
- Edge

Important NOTE: Browsers must support HTML5!

Mobile Operating Systems

• The Dream Report Web portal is supported in a web browser on Android, iOS (both iPad and iPhone) and Windows Phone 8.1 and 10.

Additional Software Requirements

- To visualize PDF files, Adobe® Acrobat or other PDF viewer should be installed (the latest versions are recommended). The Adobe® Reader installer is located in \ODS\Dream Report\Utilities\
- To use the Web Portal, a web server (Internet Information Server or other) must be installed before the Dream Report® installation. For additional information on configuring IIS for use with Dream Report,

- please refer to the Web Portal section in Help or the tech note in the Dream Report website (https://dreamreport.atlassian.net/wiki/spaces/DreamReport/)
- .NET Framework 3.5 and .NET Framework 4.72 or higher should be installed before Dream Report® installation. Please note that for the successful installation of .NET 4.72, the latest Windows updates must be applied to the operating system

Demo Version Limitations

If you have installed the AVEVA Reports Demo version (i.e., running AVEVA Reports in "Evaluation" mode, with no valid license installed,) it will have the following limitations:

- AVEVA Reports Studio will show a yellow bar indicating that "Studio is running without a license"
- AVEVA Reports runtime will run a project continuously for 30 minutes and then shut down.
- A maximum of 100 unique items (tags) is allowed
- Web portal is enabled with one concurrent web client connection
- A red line will be added on top of each report page, which says that report has been generated with the demo version of AVEVA Reports.
- For a full-featured trial license, please contact your local AVEVA distributor

Note:

Please, refer to the AVEVA Reports online help to get information about any specific functionality.
 Online help can be opened in the *Help* menu of AVEVA Reports Studio (F1) or using the Windows Start > ODS > Documentation menu.

To buy AVEVA Reports for Operations

Please contact your local AVEVA distributor

Contact Technical Support

support@dreamreport.com

Knowledge Base Website:

www.dreamreport.net/techsupport

